



## Operations Factual

Accident: **Capsizing of U.S. Small Passenger Vessel *Taki-Tooo***  
Date: June 14, 2003  
Location: Pacific Ocean, near entrance to Tillamook Bay, Oregon  
NTSB #: DCA03MM035

### Party Members

Robert Ford- Deck Operations Group Chairman  
National Transportation Safety Board

Kenneth M. Lawrenson  
Commercial Fishing Vessel Safety Coordinator  
Portland, Oregon  
U.S. Coast Guard

Peter Wood  
Sgt. Pat Rowland  
Oregon State Marine Board  
435 Commercial Street N.E. #400  
P.O. Box 14145  
Salem, Or. 97309-5065

1		
2	Accident Summary .....	3
3	Accident .....	3
4	Injuries .....	13
5	Damage .....	13
6	Personnel Information.....	13
7	Vessel Information.....	15
8	Critical Profile.....	15
9	Coast Guard Inspections .....	16
10	Vessel Survey.....	17
11	Engine Information .....	18
12	Wreckage .....	18
13	Waterway Information.....	20
14	Operational Information .....	23
15	Meteorological Information.....	24
16	Other Information .....	25
17	Tides and Tidal Currents.....	25
18	Waves and Swell.....	25
19	Taki-Toooo Chart Plotter.....	26
20	Oakland Pilot Data Card .....	27
21	Eyewitness Sketches .....	28
22		
23		
24		

## 1 Accident Summary

2 At about 0605 on the morning of June 14, 2003 <sup>1</sup>, the U.S. Charter Fishing Vessel  
3 *Taki-Tooo* departed the marina at Garibaldi, Oregon with seventeen passengers and two  
4 crewmembers on board. The vessel proceeded to an area near the entrance to Tillamook  
5 Bay and waited for the opportune sea conditions before making an attempt to depart the  
6 inlet. At about 0715 the *Taki-Tooo* departed the inlet and encountered a wave that  
7 capsized the vessel. The master and eight passengers died. Two persons were missing  
8 and presumed dead. The deckhand and remaining seven passengers washed ashore on  
9 the nearby beach and survived.

10

## 11 Accident

12 At about 0530, June 14, 2003, the master of the charter fishing vessel *Taki-Tooo*  
13 left his home and went to the Garibaldi Charters office, operators of the charter fishing  
14 vessels *Taki-Tooo*, *Norwester* and *D&D*. The master was not the regularly assigned  
15 master but had been requested by passengers that had made arrangements to go charter  
16 fishing for the day (See section on Owner).

17 According to the master's wife, there were two VHF radios in the couple's home  
18 as well as a VHF radio in the master's truck. The wife stated that the master made it a  
19 point to listen to the radio before leaving the home and while driving to the charter office.

---

<sup>1</sup> All times are based on Pacific Daylight Time (PDT), which is seven hours earlier than Universal Time.

1 He would print out weather maps on his personal computer to review forecasts for the  
2 bar.

3 The master and deckhand agreed that due to weather conditions at the bar, they  
4 would not be setting crab pots as originally planned. According to the deckhand, it  
5 would have been difficult to retrieve the pots and the master told the passengers at the  
6 charter company office that the reason the crab pots would not be set was due to the  
7 rough bar.

8 The master and deckhand went to the vessel at the marina and boarded the  
9 passengers. The master gave a safety briefing but did not demonstrate the procedure for  
10 donning a lifejacket. The deckhand described the master as being happy and was joking  
11 on the morning of the accident, which was consistent with the deckhands' perception of  
12 the master's personality.

13 The master assumed control of the vessel from the flying bridge and proceeded  
14 towards the entrance to the inlet (see waterway information for description of inlet, bar  
15 and observation tower). The *Taki-Too* proceeded past the Coast Guard observation  
16 tower shortly before 0700. A Coast Guard seaman, hereafter referred to as tower watch  
17 1, had been stationed in the tower since 0445. Another Coast Guard seaman relieved him  
18 at about 0700 and he will be referred to as tower watch 2.

19 The Coast Guard Motor Lifeboat (MLB) 47210 was on scene near the inlet at  
20 0445. The operator of the vessel was a certified coxswain that had been in the Coast  
21 Guard for eight years and had been stationed at Tillamook Bay for over five years. It was  
22 the duty of the coxswain to make an assessment of the bar conditions based on visual

1 observations and make a recommendation back to the station. After observing the  
2 conditions at the bar, the coxswain transmitted the following bar report back to Station  
3 Tillamook; Tips 6-8 sluffing and plunging: All outside areas 8-10 O/S 12 Sloughing<sup>2</sup> and  
4 Plunging; Visibility 05 Nautical Miles; Winds East @ 14 Knots.; Recommend Keeping  
5 Bar restricted to All. The Senior Duty Officer and Officer of the Day concurred and the  
6 bar was restricted to recreational traffic.

7 Commercial fishing vessels were not under the restriction (See section on  
8 waterway). A VHF Broadcast regarding the Bar restriction was transmitted at 0514 on  
9 VHF channels 16 and 22A as well as Citizens Band radio Channel 09.

10 The charter fishing vessel *Oakland Pilot* had arrived near the observation tower at  
11 about 0545. According to the master of the commercial fishing vessel *Amanda*, he  
12 arrived on scene after the *Oakland Pilot* had already arrived at the inlet but before the  
13 charter fishing vessel *Norwester* arrived near the tower at about 0620. The *Amanda* was  
14 not recorded on the Coast Guard vessel count sheet, which was maintained by the tower  
15 watch. The owner of Garibaldi Charters drove to the north jetty in order to watch the  
16 boats depart the inlet. He had arrived at about 0620 and before the *Norwester* had arrived  
17 near the tower. He stated that it was not unusual for him to go to the jetty to watch the  
18 vessels depart the bar. Another charter fishing vessel, the *D&D*, arrived at the inlet at  
19 about the same time that the *Taki-Tooo* arrived.<sup>3</sup> The *Norwester* and *Oakland Pilot*

---

<sup>2</sup> From Coast Guard technical review, correct term should have been sloughing, meaning cast off or shed.

<sup>3</sup> The times that the vessels arrived near the observation tower and inlet were taken from post-accident interviews, the Coast Guard Observation Tower Vessel Count Sheet and in the case of the *Oakland Pilot*, from trackpoint data retrieved from the vessel's chart plotter.

1 waited near the jetty tips and backed into the ebbing current. The master of the *Norwester*  
2 told Safety Board investigators that he waited for thirty to forty-five minutes before  
3 seeing a “window” to cross the bar.

4 According to the master of the *Amanda*, the *Norwester* immediately took a  
5 position on the north side of the bar, just inside from the jetty tip in an area called the soft  
6 zone. See Figure\_\_\_ for comparison of vessels. Tower watch 1 told Safety Board  
7 investigators that while he was on watch in the tower, he observed the sea conditions  
8 consisting of eight to ten waves in a series with a five to six second break or lull between  
9 sets.

Name of Vessel	Propulsion	Horsepower	Length	Breadth	Depth (feet)
<i>Norwester</i>	Twin-Screw	420	41.8	14.2	6.3
<i>Oakland Pilot</i>	Twin-Screw	730	44.4	15.3	8.6
<i>D &amp; D</i>	Single-Screw	230	32.4	12.2	5.3
<i>Taki- Tooo</i>	Single-Screw	250	32.5	12.1	5.3
<i>Kerri- Linn</i>	Single-Screw	330	29.4	12.3	5.6
<i>Amanda</i> <sup>4</sup>	Single-Screw		23.0		

10 \* All of the vessels were constructed of Fiberglass Reinforced plywood (FRP).  
1 Figure \_\_\_\_\_. Comparison of charter fishing vessels associated with the accident.

2 According to tower watch 1, he observed the *Norwester* depart the inlet at about  
3 0645 and continued to monitor the vessel’s progress as it proceeded through the bar. The  
4 *Norwester* rode over one swell and on the second break, the vessel was stood straight up  
5 or at close to a vertical angle pointing upwards. The tower watch continued to maintain

---

<sup>4</sup> The Amanda was an uninspected commercial fishing vessel.

1 visual contact with the vessel until it cleared the surf area and was out in calmer seas.  
2 The coxswain on the MLB told Safety Board investigators that the *Norwester* “took them  
3 really good,” referring to the seas. He observed the stern of the vessel “just go way up in  
4 the air and come back down.”

5  
6 According to the master of the *Norwester*, after clearing the bar, he contacted the  
7 other vessels waiting at the inlet by VHF radiotelephone channel. The transmission was  
8 not taped nor monitored by the Coast Guard tower, but the mate on the *Taki-Tooo* stated  
9 at the post accident interview with Safety Board investigators that the master of the  
10 *Norwester* called back and said that “it wasn’t worth it” and that the vessels should wait  
11 until the bar had calmed. The master of the *Norwester* also stated in his transmission  
12 that the other captains should not tell his mom that he had gone through the bar. A  
13 passenger that was standing next to the master of the *D&D* stated in a post accident  
14 interview to Safety Board investigators that the *Norwester* master stated over the VHF  
15 was “Quote, unquote, It is not worth it.” The owner of the charter company was standing  
16 on the north jetty and was monitoring the radio traffic with a hand-held VHF radio. He  
17 believed he heard the master of the *Norwester* say that it “was not worth it to do it now”  
18 and told investigators that he thought the master of the *Norwester* was addressing the  
19 master of the *Taki-Tooo*.

20 One of the passengers on board the *Taki-Tooo* was standing along the foredeck of  
21 the vessel and close to the master at the flying bridge controls. The passenger stated to  
22 Coast Guard investigators during an interview conducted on the afternoon of the accident  
23 that he heard the master of the *Norwester* say over the radio that he had to avoid hitting a

1 log and that “it wasn’t worth it.” At the post accident interview with Safety Board  
2 investigators, the master of the *Norwester* said that there were “logs all over the tips and  
3 stuff.”

4  
5 About five minutes after the *Norwester* cleared the bar, the *Oakland Pilot*  
6 proceeded past the jetty tips to cross the bar. The vessel experienced similar conditions to  
7 the *Norwester*. One passenger was thrown against a window and his elbow broke the  
8 window. (See section on Oakland Pilot’s Chart Plotter Data for description of trackline  
9 over bar.) The deckhand of the *Taki-Too* told Safety Board investigators that the master  
10 of the *Oakland Pilot* called back on the VHF radio after clearing the bar and said that he  
11 had to dodge a log and that there were “a lot of logs floating out there.”

12 At about 0700, a second Coast Guard seaman reported to the tower to assume the  
13 watch. He will be referred to watch 2. According to watch 1, the turnover between the  
14 two seamen lasted less than two minutes. Watch 1 informed watch 2 that the surf was  
15 pretty rough and that watch 2 had just missed some “cowboy stuff pulled off by the  
16 *Norwester* and *Oakland Pilot*.” Watch 1 also remarked to watch 2 that the *Norwester*  
17 was stood straight up as it proceeded through the bar.

18 The *D&D* was the next vessel to make the transit through the bar and departed  
19 about 0700. According to a passenger that stood next to the master, the vessel was  
20 staying on the north side of the channel where the seas were not breaking. The passenger  
21 stated that before the vessel departed the inlet, the master was looking for the lull for the  
22 vessel to make his run through the bar. Without any verbal warning, the master increased  
23 propulsion and according to the passenger, “we just kind of took out, we went straight



1 west and then we turned north out to the end of the jetty.” The vessel went over about  
2 two, or three good waves, and the passenger thought that the master was about to turn  
3 west again. The passenger saw a log the size of a tree coming in with the next wave, and  
4 he thought the master turned back towards the north to maneuver around the log. The  
5 vessel continued towards the northwest and took one swell over the bow and continued  
6 on its intended route out of the bar area. At the post accident interview with Safety Board  
7 investigators, the master had no recollection of logs or debris within the bar area. He  
8 recalled a radio conversation between the *Norwester* and *Oakland Pilot* and that referred  
9 to debris in the water, yet he did not see any logs until he was clear of the bar in deeper  
10 water.

11 The *Taki-Tooo* was the only remaining charter vessel at the inlet entrance after the  
12 *D&D* departed. The master of the *Amanda* did not intend to attempt to cross the bar and  
13 remained to watch the *Taki-Tooo* cross the bar. According to the deckhand of the *Taki-*  
14 *Tooo*, the master made about six circles starting near the tower and would edge out  
15 towards the jetty tips. The deckhand stated that the vessel never made it to the jetty tips  
16 while making the circles to assess the bar conditions. The master would maneuver the  
17 vessel from the tower to about three quarters of the way to the jetty and then back around  
18 again in a circle to near the tower. While making the circles, the deckhand noticed that as  
19 the other vessels departed the inlet, “if they waited until it looked good, you wouldn’t get  
20 there in time for it to be good, so you had to kind of inch out there while it wasn’t good.”

21 The owner of the charter company told Safety Board investigators that on the  
22 morning of the accident, he could identify the sets of waves as, “ you have got two large  
23 waves usually and then five or six smaller ones and then a large one for the sets.” He

1 also stated that the distance between large waves meant that a vessel “wasn’t going to  
2 allow you to make it all the way out without going over at least one of those bigger  
3 ones.” The owner repeated what the deckhand had told investigators. The masters had to  
4 depart the jaws of the jetty when the seas were not good to be in position at the bar for  
5 when the seas were good.

6 The deckhand joined the master on the flying bridge immediately prior to  
7 departing the inlet. According to the deckhand, the vessel departed the inlet, rode over  
8 one swell and saw that the waves were getting bigger instead of smaller. According to  
9 the deckhand, the master remarked, “he did not want to get into this”. The deckhand  
10 believed the master put the engines in reverse or astern power so the vessel “ didn’t go  
11 flying off the other end” of the wave. She stated that the boat twisted to the north and the  
12 swell was coming from the west. The deckhand stated that the vessel never lost power  
13 and she would have known if it had.

14 The passenger that had been standing on the foredeck had returned to the cabin.  
15 He told Coast Guard investigators that the boat was running fine but the master “got into  
16 some debris or logs and had to back out of it. He lost power and he powered back up.”  
17 The third swell was about twenty feet in height and he could “see it coming.” He stated  
18 that the master turned the vessel north around the jetty for what he referred to as the  
19 “third roller” which capsized the vessel. He believed that the master made a “judgement  
20 call” in not making another turn and have all passengers don a lifejacket. He never  
21 thought the master would turn the vessel to take the swell “broadside.”

22 The master of the *Amanda* stated at the post accident interview that he watched

1 the *Taki-Tooo* and it didn't look to him "like the vessel was being pushed. It looked to  
2 him like the master of the *Taki-Tooo* "just backed off the throttle some, turned and hit his  
3 throttle again to go north, you know, to get off of the bar."

4 Another eyewitness to the capsizing was the owner/master of the charter fishing  
5 vessel *Kerri Lin*. The owner/master cancelled his charter for the day due to the sea  
6 conditions at the bar. His policy was that once the sea exceeded double digits, meaning  
7 ten feet, he would not operate. The owner/operator had gone to breakfast and heard over  
8 a hand-held VHF radio some "chatter" between the boats at the bar. He decided to go to  
9 the north jetty to watch as the vessels departed the inlet. He arrived as the *D&D* started  
10 out through the bar. He told Safety Board investigators that the master of the *D&D* never  
11 hurried is departure track and "didn't have any trouble at all" going past the bar.

12 He continued to watch as the *Taki-Tooo* departed the inlet and saw the vessel go  
13 over a ten or twelve foot wave. He believed the master of the *Taki-Tooo* throttled down  
14 or reduced speed, which he stated should have allowed the wave to roll underneath the  
15 vessel and prevent the vessel from crashing down on the backside of the wave. However,  
16 instead, he said the vessel "backed down and it kind of went sideways." He thought the  
17 master of the *Taki-Tooo* gave more power to the engines as the vessel rolled up and in the  
18 curl of a 12 to 15 foot sea that he described as a "monster". The vessel capsized  
19 throwing the passengers standing on the stern of the boat into the sea. One passenger  
20 stated that he was thrown into the cabin, but could not explain how it happened.

21

22 The Coast Guard tower watch 2 observed the *Taki-Tooo* depart the inlet and  
23 followed the track of the vessel by looking through the "big eye" binoculars. He told

1 Safety Board investigators that he had never seen a vessel pass as close to the northern tip  
2 of the jetty as the *Taki-Tooo*. He saw a second swell that was breaking and the force of  
3 the swell capsized the vessel. Tower Watch 2 stated that the swell did not break on the  
4 *Taki-Tooo*.

5

6

7 The coxswain of the MLB watched the *Taki-Tooo* depart the inlet and observed  
8 him pass “really close to the north tip.” He lost visual contact of the *Taki-Tooo* and  
9 waited until the tower watch told him that the vessel had capsized.

10 The tower notified the MLB that the *Taki-Tooo* had capsized. The operator of the  
11 MLB told safety Board investigators that he waited about one minute before he felt he  
12 could get safe passage out across the bar. He could not identify a lull and could only see  
13 breakers that were very steep. He described the seas as “ really, really choppy and big ”  
14 and said that the MLB had to travel over a swell he estimated at about 14 feet. He also  
15 stated that the swells were breaking and the entire area around the bar was whitewater.

16 After clearing the inlet, he remembered that he was not qualified to attempt a  
17 rescue in the surf. He felt that the *Taki-Tooo* was very close to the rocks and any attempt  
18 to approach the capsized vessel would have endangered his vessel. He estimated that he  
19 was within 50 to 75 yards from the jetty tip as opposed to the typical 100 yards distance  
20 from the jetty.

21 At 0725 PDT, the Coast Guard’s District 13 Rescue Coordination Center (RCC)

1 received a distress alert from an EPIRB<sup>5</sup> registered to the vessel *Taki-Tooo*. At 0730, the  
2 RCC received confirmation from Station Garibaldi that the vessel had capsized with 19  
3 persons in the water. A Coast Guard 47210 rescue boat was reported underway with a  
4 second 47210 and helicopter launched.

## 5 Injuries

6 See Survival Factors Factuals.

7

## 8 Damage

9 The Taki-Tooo had an estimated market value of \$60,000 and replacement value  
10 of \$180,000.<sup>6</sup>

11

## 12 Personnel Information

13 The master of the *Taki-Tooo* on the day of the accident was the owner of the  
14 vessel. He was 66 years old and had lived and operated charter fishing boats in the  
15 Tillamook area for 15 years. He was the previous owner of Garibaldi Charters.

16

17 The master had operated under a U.S. Coast Guard license since March 1984.

18 See table below. Applicants for the issuance of an original license included proof of

19

---

<sup>5</sup> Emergency Position Indicating Radio Beacon.

<sup>6</sup> The values are based on a September 2002 survey performed by a marine surveyor.

<b>Issue Number</b>	<b>License Held</b>	<b>Issue Date</b>
1	To Operate or Navigate Passenger Carrying Vessels of not more than 50 gross tons upon the Pacific Ocean not more than 50 miles offshore	March 19, 1984
2	Master Near Coastal Steam or Motor Vessels Of Not more than 50 Gross Tons	January 4, 1989
3	Master Near Coastal Steam or Motor Vessels of Not more than 50 Gross Tons	January 24, 1994
4	Master Near Coastal Steam or Motor Vessels of Not More than 100 Gross Tons	March 3, 1999

1

2 qualifying experience for the appropriate tonnage or horsepower. The application  
3 provided by the Coast Guard indicated that the master had 122 eight-hour days in the  
4 preceding three years before applying for his original license. The application also  
5 indicated that the master had over 700- eight-hour days of experience operating small  
6 passenger vessels upon the Pacific Ocean from Tillamook Head, Oregon to Leadbetter  
7 Point, Washington. In order to renew his license, the master had to prove that he had one  
8 year experience in the previous five years on vessels of the appropriate tonnage or  
9 horsepower .<sup>7</sup> According to the records submitted to the Coast Guard, from March 1984  
10 until renewal of his license in March 1999, all of the master's experience was on the  
11 *Taki-Tooo* in waters of the Pacific Ocean starting from Tillamook Bay. See the table  
12 below for his sea service records.

<b>Vessel/Length</b>	<b>Dates</b>	<b>Sea Service Days</b>
We-O-Sum / 24 feet	1976 to 1981	465
Cat- Meow / 24 feet	1981	84
Taki-Tooo / 32.5 feet	1982 to 1983	193
Taki-Tooo	1984 to 1988	395
Taki-Tooo	1989 to 1993	466
Taki-Tooo	1994 to 1998	551

---

<sup>7</sup> 46CFR 10.209 (i).

1

2       The master was required to have a physical examination in accordance with  
3 46CFR in order to renew his license. His most recent examination was February 17,  
4 1999. The master had been treated for prostate cancer in 1993 and tongue cancer in 1989.  
5 The master was on medication for high blood pressure. The examining physician found  
6 the master competent to perform the duties to be performed on board a merchant vessel.

7

8       The records indicated that the master's vision was corrected to 20/20 and his field  
9 of vision was normal.

10

11       The 22 year old deckhand was the charter owner's daughter. She had worked as  
12 a deckhand for five years and had begun her career working with the master on the *Taki-*  
13 *Tooo*. She had worked with her brother, the master of the *Norwester*, for three summers  
14 and returned to the Taki-Tooo the summer of 2003. The trip of the capsizing was the first  
15 trip she had made with the particular master that season.

16

## 17 Vessel Information

### 18 Critical Profile

19

20	Official Number	579874
21	Hull Number	35-707
22	Year Built	1977
23	Registered Length	32.5
24	Gross Registered Tons	14
25		
26	Total Persons Allowed on Board	22

1

2           The *Taki-Tooo* was a charter fishing boat that was inspected by the Coast Guard  
3 to comply with 46CFR Subchapter T. The *Taki-Tooo* was manufactured by Modutech  
4 Marine Inc of Tacoma Washington. According to the company sales brochure, the vessel  
5 was a 36 foot charter fishing boat with a flying bridge, cabin and open deck on the stern.

6

7           The following measurements were taken by Safety Board investigators:

8                   Cabin	7.5 feet long by 8.75 feet wide
9                   Aft Open Deck	18.5 feet long by 12 feet wide
10                  Open Bow	6 feet long by 9 feet wide

11

12           The vessel was owned by Davis Fisheries, Inc. and was operated by Garibaldi  
13 Charters. According to the U.S. Coast Guard Certificate of Inspection, the vessel was  
14 required to be manned with one Coast Guard licensed master and one deckhand. The  
15 route permitted was “Pacific Ocean between Point St. George, California, and Angeles  
16 Point, Washington, Not more than 100 miles from land.”

17           A Simplified Stability Test, supervised by the Coast Guard, was performed on the  
18 vessel on 24 April 1990.<sup>8</sup>

#### 19 Coast Guard Inspections

20

21           The vessel had undergone a Coast Guard drydock inspection November 29, 2001.  
22 A complete hull examination was conducted and the only deficiency noted was that the  
23 owner had to repair a leak entering forward compartment from kingpost located on main

---

<sup>8</sup> The Simplified Stability Test, described by pre-1996 changes to the Small Passenger Vessel regulations in 46 CFR 171.030.



1 deck. The item had to be accomplished before the vessel could carry passengers.

2  
3 The *Taki-Tooo* had undergone an Annual inspection in March, 2003. Eight  
4 deficiencies were noted as follows:

- 5 1. Renew the 100 foot life line that connects the weak link to the buoyant  
6 apparatus.
- 7 2. Renew the lanyard attaching the float light to the buoyant apparatus.
- 8 3. Prove proper operation of the fixed fire extinguisher system once re-installed.
- 9 4. Prove proper operation of the bilge high water alarm for both the engineroom  
10 and steering compartment.
- 11 5. Provide guard over battery terminal to protect them from hatch cover.
- 12 6. Prove proper operation of the mast head light.
- 13 7. Label the bilge manifold to show what compartment they serve.
- 14 8. Provide new Rules of the Road Book.

15 All of the deficiencies were cleared April 23, 2003.

#### 16 Vessel Survey

17

18 All Boats, Ltd. Marine Surveyors conducted a valuation survey on the *Taki-Tooo*  
19 in September 2002. The survey was conducted while the vessel was in the water.  
20 According to the survey, the vessel's estimated value was \$60,000 with an estimated  
21 replacement value of \$180,000.

22  
23 The hull, cabin and flying bridge were constructed of fiberglass reinforced plastic  
24 (FRP). The decks were built of plywood with FRP cover and wood frames. The bow was  
25 raked with single hard chines.

26  
27 The vessel had a 4-bladed 26" diameter right-handed bronze propeller.

1 Wheelhouse Electronic and Equipment

2  
3 1 24 Mile Range Radar  
4 2 VHF Radios  
5 1 Citizen's Band Radio  
6 1 Single Sideband Radio  
7 1 Magnetic Compass  
8 1 Loran C  
9 1 GPS  
10 1 Chart Plotter

11  
12 According to the owner, the flying bridge also had a Chart plotter, magnetic  
13 compass and VHF radio.

14  
15  
16  
17  
18 Engine Information

19  
20 The boat was powered by a single diesel engine with reduction gear, shaft to  
21 propeller. The engine data was as follows:

22  
23 Manufacturer John Deere  
24 Model 6076AFM30  
25 Installed 1998  
26 Horsepower per RPM's 300 at 2200

27  
28  
29 Wreckage

30 According to passengers on the *Taki-Too*, the vessel capsized and made a second  
31 complete roll and ended upside down. The flying bridge operating console was missing  
32 and not recovered. Deck railings on the bow were bent and knocked loose from their  
33 mountings. Safety Board investigators found no evidence of damage to the vessel's hull.

1

2           The propeller was examined on scene and found to have suffered damage to its  
3 four blades. The propeller was sent to the NTSB laboratory in Washington, D.C. for  
4 examination and documentation of damage. The propeller had been stamped on the hub  
5 facing aft with the marking “22RH” and the Serial number AX566.measurement. The  
6 propeller’s four blades curled in the forward direction with the total angle of the curl and  
7 the area over which the curl occurred increased in the counter clockwise direction while  
8 looking forward.

9

10          Safety Board investigators made a post-accident inspection of the vessel with  
11 emphasis on the propulsion and steering components. The rudder and rudder post  
12 appeared to be solidly mounted and undamaged. The propeller shaft was straight and  
13 unremarkable.

14

15          The diesel engine was found intact, with no signs of oil leaks or any obvious sign  
16 of catastrophic failure. All fuel lines, fittings, and linkages were intact and attached.

17

18          The throttle and transmissions control were manipulated at the lower helm station,  
19 and they moved the throttle linkage throughout its range. The lower helm station wheel  
20 was turned in both directions and turned freely.

21

22

23

24

## 1 Waterway Information

2 The entrance to Tillamook Bay is located 42 miles south of the Columbia River  
3 and is protected by jetties to the north and south. See figure \_\_\_\_\_. The north jetty extends  
4 800 yards offshore with the westernmost section (of about 100 yards) of both jetties  
5 submerged.<sup>9</sup> A lighted whistle buoy is located about 1.2 nautical miles from the north  
6 jetty in a depth of water that is over 100 feet. The channel within the protected jetty area  
7 runs in an east-west direction.

8  
9 The entire area between the beach and the 20 foot curve is considered the bar  
10 area.<sup>10</sup> The bar area extends out .6 mile from the jetty tips to buoy “1”. A crescent-  
11 shaped or curved area of shoals with depths of less than 30 feet was located between the  
12 jetty tips and buoy “1” and was referred to as the middle ground. The area was  
13 unpredictable and considered hazardous because it was the area that the incoming seas  
14 would tend to break at due to the shallow water. After clearing the north jetty tip, there  
15 is a section of deep water between the middle ground and shallow area towards the beach  
16 that is referred to as the north hole. A vessel could follow a northwesterly course to  
17 follow the channel and narrow stretch of deep water as indicated in figure \_\_\_\_\_. There was  
18 a similar stretch of deep water to the south of the jetty tips that was referred to as the  
19 south hole. The water depths in this area are deeper than the surrounding shallow bar.

20

21 The water depth decreased slightly until .6 of a mile from the inlet where the 60

---

<sup>9</sup> Boating in Coastal Water. Pg.20 Published by Oregon State Marine Board Revised June 2001.

<sup>10</sup> A bank or shoal usually at the mouth of a river obstructing the entrance or rendering it difficult.

meter depth contour was located. The area is a patch of shoals within a 30 foot depth contour.

The Army Corps of Engineers is charged by Congress to maintain an 18-foot deep channel over the ocean bar at the entrance of Tillamook Bay. Dredging was last performed in 1976 and annual surveys have indicated that the channel has remained within its authorized depth. “The jetties are pinched which results in the jetties acting like a pinched water hose nozzle to flush sediment out the narrow entrance to deep water.”<sup>11</sup> The Corps was scheduled to survey the channel in July 2003 but moved it to the third week of June 2003 to assist in the investigation into the capsizing of the *Taki-Too*. The survey showed that the channel was within the 18 foot depth. Any future channel dredging would require funding through Congressional action.<sup>12</sup>

Coast Guard Station Tillamook Bay was a designated Surf Station. The criteria for designating a station as a surf station was based on two components: environment and frequency of surf.

Environment: Surf stations are designated in areas where surf is greater than eight feet, on a federally mandated navigable bar or entrance, of sufficient water depth to allow the operation of a surf capable boat.

Frequency of Surf: Surf stations are designated in areas where surf greater than eight feet occurs ten per cent or more during a calendar year (36 days) averaged over a minimum period of five years.<sup>13</sup>

---

International Maritime Dictionary 2<sup>nd</sup> Edition

<sup>11</sup> [www.nwp.usace.army.mil/issues/tillamook/welcome.htm](http://www.nwp.usace.army.mil/issues/tillamook/welcome.htm) March 24, 2004

<sup>12</sup> [www.nwp.usace.army.mil/issues/tillamook/welcome.htm](http://www.nwp.usace.army.mil/issues/tillamook/welcome.htm) March 24, 2004

<sup>13</sup> U.S. Coast Guard Boat Operations and Training (BOAT) Manual Volume I. COMDINST M16114.32

1  
2  
3 Tillamook Bay Bar was a regulated boating area<sup>14</sup> that defined boats as any  
4 vessels used for non-commercial purposes or operated as an uninspected passenger vessel  
5 subject to the requirements of 46 CFR chapter I, subchapter C.<sup>15</sup> The term “other unsafe  
6 condition” included boats operated in a regulated boating area when the following  
7 conditions existed:

8 (1) The wave height within the Regulated Boating area was four feet or greater;

9 or

10 (2) The wave height within the Regulated Boating Area was equal to or greater  
11 than the wave height determined by the formula  $L/10+F=W$  where

12  
13 L equaled overall length of boat in feet, F was the minimum freeboard when  
14 measured from the lowest point along the upper strake edge to the surface of the  
15 water. W was the maximum wave height in feet to the nearest highest whole  
16 number.<sup>16</sup>  
17

18 The Coast Guard had established rough bar advisory signs that were diamond  
19 shaped, painted white with an international orange border and with the words “Rough  
20 Bar” in black letters. The sign is equipped with two quick flashing yellow lights that will  
21 be activated when seas exceed four feet in height and are considered hazardous for small  
22 boats.<sup>17</sup> The signs were located on the north side of the channel at the Coast Guard  
23 station and on the observation tower.  
24

25 Vessel movement at the Tillamook Bar was monitored by a Coast Guard seaman  
26 stationed in an observation tower located on the north side of the inlet about nine hundred

---

<sup>14</sup> 33CFR 177.08 (f).

<sup>15</sup> 33 CFR 177.03 Definitions.

<sup>16</sup> 33 CFR 177.07 (f).

1 yards east from the north jetty tip. The tower was manned during daylight periods from  
2 about one half hour before sunrise and remained manned when the hazardous bar light  
3 was lit. The tower was about 68 feet high with VHF radio, hand held binoculars and  
4 tripod mounted “big eyes” binoculars. The “big eyes” magnification were 25 X 150 mm  
5 lens.

6 The 47' motor lifeboat is designed as a first response rescue resource in high seas,  
7 surf & heavy weather environments. They are built to withstand the most severe  
8 conditions at sea and are capable of effecting a rescue at sea even under the most difficult  
9 circumstances. They are self-bailing, self-righting, almost unsinkable, and have a long  
10 cruising radius for their size. It is the replacement for the aging 44' MLB fleet. There are  
11 (presently) 81 operational, being added to monthly. The total (to be delivered over 5  
12 years) will be about 200.

### 14 Operational Information

15 The master of the *Taki-Tooo*, and the master's wife had owned Garibaldi Charters  
16 and the *Taki-Tooo* and the *D&D* for approximately 15 years. In March 2001, the master  
17 and his wife had sold Garibaldi Charters to another charter vessel operator; however, they  
18 retained ownership of the two vessels. A term of the sale stipulated that the *Taki-Tooo*  
19 and *D&D* would be leased to and operated by Garibaldi Charters.

21 Garbibaldi Charters would provide whalewatching trips, occasional weddings,

---

<sup>17</sup> U.S. Coast Pilot 7- pg. 408.

1 scattering of ashes and fishing. The season went from March until October and was  
2 dictated by the weather. According to the owner of Garibaldi Charter, the weather did  
3 not permit regular trips from October until March.

4 The owner of Garibaldi Charters was the usual master on board the *Taki-Too*.  
5 However, a charter group that had made reservations to fish on board had requested that  
6 the owner be the master on the day of the accident.

7 Garibaldi Charters owned the *Norwester*, the first vessel to depart the inlet on the  
8 day of the accident.

#### 9 10 Meteorological Information

11 The National Weather Service Portland, Oregon at 1645 June 13, 2003 issued the  
12 following forecast for coastal waters for southern Washington and northern Oregon  
13 Coast: A weak PAC front will brush across the Northern waters Saturday. High Pres  
14 will rebuild in the N on Sun. The forecast called for small craft advisory for hazardous  
15 seas for the same evening and the following conditions: "S wind 20 knots. Wind waves  
16 four feet. West swell 10 feet at 11 seconds.. The forecast predicted 12 foot swells for Sat  
17 and 14 second period."<sup>18</sup>

18 According to the meteorologist-in-Charge at the Portland, Oregon National  
19 Weather Service Office, the Small Craft Advisory for Hazardous Seas was issued at  
20 1645, June 13, 2004, Pacific Daylight Time.

---

<sup>18</sup> Forecasts were for ocean conditions.



1 A National Weather Service anemometer was mounted on the observation tower  
2 and wind directions and speeds were recorded. At 0700 to 0730 the wind direction was  
3 from a southeasterly direction at about ten knots.

4 The master of the *Amanda* told Safety Board investigators that there was a swell  
5 from the west, another smaller swell from the northwest and a swell from the southwest.  
6 At certain times the three swells would join and form one large swell.

## 7 8 Other Information

### 9 Tides and Tidal Currents 10

11 The soundings at Tillamook Bay Inlet and Bar that are represented on NOAA  
12 Chart 18558 are for the depths of water at Mean Lower Low Water (MLLW). There was  
13 a full moon at 0417 Pacific Daylight Time (PDT) on June 14, 2003.<sup>19</sup> According to  
14 Tide Tables that were provided by local merchants as well as on line tide software  
15 [www.tides.com](http://www.tides.com), there was a negative tide of 2.1 feet on the morning of the accident.

16 The tide was near the end of the ebb tide<sup>20</sup> at the time of the accident, which was  
17 0721 for Tillamook Beaches and bar.

### 18 Waves and Swell 19

---

<sup>19</sup> aa.usno.navy.mil/cgi-bin/aa\_pap.pl.

<sup>20</sup> Ebb tide is when the flow of water is toward the sea.

1 Wind is the principal factor that causes waves on the earth. The resulting waves  
2 caused by the prevailing winds are referred to as sea.<sup>21</sup> Swells on the other hand are  
3 wind-generated waves that have continued on out of the area of generation.<sup>22</sup> As the  
4 waves or swells enter shallow water, the friction of the bottom will tend to slow down the  
5 water particles near the bottom while the upper water particles continue at the faster  
6 velocity. The difference in speed between the upper and lower wave will cause the wave  
7 to steepen and then break.<sup>23</sup> The breakers fall into three classes. A spilling breaker  
8 breaks gradually and over a considerable distance. A plunging breaker tends to curl over  
9 and break in a single crash. A surging break peaks up, but surges on the beach without  
10 spilling or plunging.

11 The Oregon State Marine Board, in describing hazards crossing the Tillamook  
12 Bar, states,

13 *One of the greatest risks a boater can encounter is getting caught in a shallow*  
14 *river entrance to the Pacific - the bar – when a swift ebb current is meeting*  
15 *incoming westerly waves. Such conditions result in the two opposing forces*  
16 *meeting to pile up water and waves that break with tremendous force.*<sup>24</sup>

17  
18  
19  
20 *Taki-Tooo* Chart Plotter

21 The *Taki-Tooo's* chart plotter was retrieved and sent to the manufacturer in an  
22 attempt to retrieve the vessel's track data. The evaluation showed the unit to have been

---

<sup>21</sup> Bowditch American Practical Navigator

<sup>22</sup> Weather for the Mariner, Kotsch pg.133

<sup>23</sup> Ibid. pg. 133

<sup>24</sup> [www.marinebd.osmb.state.or.us/Coastal Waters/Safety1.htm](http://www.marinebd.osmb.state.or.us/Coastal%20Waters/Safety1.htm) May 17, 2005

1 completely waterlogged with all components damaged, consistent with the unit having  
2 been submerged. The salt water intrusion, along with the length of time the unit sat prior  
3 to receipt at by the manufacturer had completely damaged all internal components, thus  
4 rendering the data irretrievable.

5  
6  
7 *Oakland Pilot* Data Card

8  
9 The fishing vessel *Oakland Pilot* had a Garmin Chart Plotter with Global  
10 Positioning System (GPS) input. The unit had the function of downloading recent data  
11 on to a data saver card. Safety Board investigators downloaded the data on to the card  
12 and sent the card for extraction to the manufacturers headquarters. The information was  
13 plotted on the nautical chart for the inlet. See appendix\_\_\_\_ for the positions, times,  
14 course and speeds of the *Oakland Pilot* for the date of the accident.

15  
16 The data showed that the first recorded track at 12:29:19 PM (UTC), which would  
17 have been 0529 local on June 14, 2003. The data indicated that the vessel was off the  
18 jetty tips at about 0545 and maintained station using various courses and speeds. At  
19 about 0656, the *Oakland Pilot* increased speed to over 12 knots and proceeded past the  
20 jetty tips on a magnetic course of 278°. Within seconds of clearing the jetty, the vessel  
21 turned towards the north-northwest to an area that was east of the north hole. The  
22 vessel's track remained east of the north hole until clearing the bar in deeper water. See  
23 figure\_\_\_\_.

1 Eyewitness Sketches

2           During the on-scene investigation, Safety Board investigators requested  
3 eyewitnesses to sketch the tracks of the four vessels that departed the inlet on the  
4 morning of the accident. The sketches were done by the owner of Garibaldi Charter, the  
5 owner/master of the *Kerri Lin*, and Watch tower 2.

6           The owner of Garibaldi charter positioned the five vessels within the jetty tips  
7 with the *Norwester* and *Oakland Pilot* at the farthest point to the west of the inlet. The  
8 *Taki-Tooo* and *D&D* remained further in. The routes of the vessels were sketched  
9 showing the *D&D* taking the track furthest to the west, with the *Norwester* and *Oakland*  
10 *Pilot* closer to the jetty on a similar track. The *Taki-Too's* track was the closest to the  
11 north jetty tip.

12           The watch tower 2 was walking up the tower steps to relieve watch tower 1 when  
13 the *Oakland Pilot* departed the inlet. He did not see the *Norwester* cross the bar. His  
14 sketch indicated the *Oakland Pilot* as taking the western most track with the *D&D* more  
15 to the east, followed by the *Taki-Tooo* as closest to the north jetty tip. The sketch of the  
16 track of the *Oakland Pilot* indicated that the vessel remained east of the north hole, which  
17 was consistent with the chart plotter information.

18           The sketch provided by the owner/master of the *Kerri-Lin* indicated the trackline  
19 of the *Taki-Tooo* as closer to the north tip of the jetty than the *D&D*. He did not witness  
20 the *Norwester* or *Oakland Pilot* depart the inlet.

21